



# Escort 5511X Soil Compactor 2023

Escorts 5511X · Rajpura, Punjab

CURRENT MARKET VALUATION

**25,00,000** ~~27,00,000~~

Regional logistics and setup excluded.

## — Vehicle Inspection & Documentation Report

Intro Line: Comprehensive 150-point inspection report and legal documentation verification for asset transparency.

### Vehicle Overview

ASSET ID  
AIE-00059

CATEGORY  
Compactor

BRAND  
Escorts

MODEL  
5511X

YEAR  
2023

ODOMETER  
1,100 Hours

FUEL TYPE  
Diesel

OWNERSHIP  
First Owner

LOCATION  
Rajpura, Punjab

 **RTO & Documentation**

|                       |                     |                  |                |
|-----------------------|---------------------|------------------|----------------|
| RC STATUS<br>Verified | INSURANCE<br>Active | FITNESS<br>Valid | MV TAX<br>Paid |
| BLACKLISTING<br>None  | CHALLANS<br>Clear   | MORTGAGE<br>No   | NOC<br>Yes     |

**General Condition**

|                   |               |
|-------------------|---------------|
| Running Condition | Yes           |
| Body Type         | Standard      |
| Cabin Paint       | Original      |
| Accidents         | None Reported |

**Accessories & Spares**

|            |   |
|------------|---|
| Stepney    | — |
| Toolkit    | ✓ |
| Battery    | ✓ |
| Floor Mats | — |

**Exterior & Chassis**

|                |          |
|----------------|----------|
| Chassis Number | Verified |
| RC Match       | Matched  |
| Imprint        | Clear    |
| Rust/Corrosion | None     |

**Cabin & Electrical**

|                   |   |
|-------------------|---|
| Glass/Windows     | — |
| Lights/Indicators | ✓ |
| Seats/Upholstery  | ✓ |
| Mirrors           | — |

 **Engine & Transmission Performance**

|                      |                        |                         |                        |
|----------------------|------------------------|-------------------------|------------------------|
| BATTERY<br>Excellent | ENGINE SOUND<br>Normal | EXHAUST SMOKE<br>Clean  | ACCELERATION<br>Linear |
| CLUTCH<br>Soft       | GEAR SHIFT<br>Smooth   | GEARBOX SOUND<br>Silent | COMPRESSION<br>High    |

**Tyre Condition Report**



