



# JCB 530-110 Telehandler – 2022 Model

JCB 530-110 · Gorakhpur, Uttar Pradesh

CURRENT MARKET VALUATION

**22,00,000** 24,00,000

 Regional logistics and setup excluded.

## — Vehicle Inspection & Documentation Report

The exact engine and configuration can vary by market/version, so the serial number or specification plate should be checked before publishing exact technical claims. JCB confirms the 11 m lift height and 3,000 kg lift capacity for the 530-110.

### Vehicle Overview

|                       |                          |                                      |
|-----------------------|--------------------------|--------------------------------------|
| ASSET ID<br>AIE-00076 | CATEGORY<br>Telehandler  | BRAND<br>JCB                         |
| MODEL<br>530-110      | YEAR<br>2022             | ODOMETER<br>4,500 Hours              |
| FUEL TYPE<br>Diesel   | OWNERSHIP<br>First Owner | LOCATION<br>Gorakhpur, Uttar Pradesh |

 **RTO & Documentation**

|                       |                     |                  |                |
|-----------------------|---------------------|------------------|----------------|
| RC STATUS<br>Verified | INSURANCE<br>Active | FITNESS<br>Valid | MV TAX<br>Paid |
| BLACKLISTING<br>None  | CHALLANS<br>Clear   | MORTGAGE<br>No   | NOC<br>Yes     |

**General Condition**

|                   |               |
|-------------------|---------------|
| Running Condition | Yes           |
| Body Type         | Standard      |
| Cabin Paint       | Original      |
| Accidents         | None Reported |

**Accessories & Spares**

|            |   |
|------------|---|
| Stepney    | — |
| Toolkit    | ✓ |
| Battery    | ✓ |
| Floor Mats | ✓ |

**Exterior & Chassis**

|                |          |
|----------------|----------|
| Chassis Number | Verified |
| RC Match       | Matched  |
| Imprint        | Clear    |
| Rust/Corrosion | None     |





**Cabin & Electrical**

|                   |   |
|-------------------|---|
| Glass/Windows     | ✓ |
| Lights/Indicators | ✓ |
| Seats/Upholstery  | ✓ |
| Mirrors           | ✓ |

 **Engine & Transmission Performance**

|                      |                        |                         |                        |
|----------------------|------------------------|-------------------------|------------------------|
| BATTERY<br>Excellent | ENGINE SOUND<br>Normal | EXHAUST SMOKE<br>Clean  | ACCELERATION<br>Linear |
| CLUTCH<br>Soft       | GEAR SHIFT<br>Smooth   | GEARBOX SOUND<br>Silent | COMPRESSION<br>High    |

**Tyre Condition Report**





Processed using the free version of Watermarkly. The paid version does not add this mark.