



# TATA 210LC Excavator (2022)

TATA Hitachi 210LC · Dausa, Rajasthan

CURRENT MARKET VALUATION

**29,00,000** ~~32,00,000~~

 Regional logistics and setup excluded.

## — Vehicle Inspection & Documentation Report

### Vehicle Overview

|                          |             |                  |
|--------------------------|-------------|------------------|
| ASSET ID                 | CATEGORY    | BRAND            |
| ASID-00009-1784186493773 | Excavator   | TATA Hitachi     |
| MODEL                    | YEAR        | ODOMETER         |
| 210LC                    | 2022        | 4,000 Hours      |
| FUEL TYPE                | OWNERSHIP   | LOCATION         |
| Diesel                   | First Owner | Dausa, Rajasthan |

 **RTO & Documentation**

|                       |                     |                  |                |
|-----------------------|---------------------|------------------|----------------|
| RC STATUS<br>Verified | INSURANCE<br>Active | FITNESS<br>Valid | MV TAX<br>Paid |
| BLACKLISTING<br>None  | CHALLANS<br>Clear   | MORTGAGE<br>Yes  | NOC<br>Yes     |

**General Condition**

|                   |               |
|-------------------|---------------|
| Running Condition | Yes           |
| Body Type         | Excellent     |
| Cabin Paint       | Original      |
| Accidents         | None Reported |

**Accessories & Spares**

|            |   |
|------------|---|
| Stepney    | — |
| Toolkit    | — |
| Battery    | — |
| Floor Mats | — |

**Exterior & Chassis**

|                |          |
|----------------|----------|
| Chassis Number | Verified |
| RC Match       | Matched  |
| Imprint        | Clear    |
| Rust/Corrosion | None     |

**Cabin & Electrical**

|                   |   |
|-------------------|---|
| Glass/Windows     | — |
| Lights/Indicators | — |
| Seats/Upholstery  | — |
| Mirrors           | — |

 **Engine & Transmission Performance**

|                      |                        |                         |                        |
|----------------------|------------------------|-------------------------|------------------------|
| BATTERY<br>Excellent | ENGINE SOUND<br>Normal | EXHAUST SMOKE<br>Clean  | ACCELERATION<br>Linear |
| CLUTCH<br>Soft       | GEAR SHIFT<br>Smooth   | GEARBOX SOUND<br>Silent | COMPRESSION<br>High    |

**Tyre Condition Report**



